HARS MD. 2-ANNA

31.

King William School (Workman House) 10 Francis Street Annapolis Anne Arundel County Maryland

### PHOTOGRAPHS

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20013

King William's School (Anthony Workman Inn)
(Donaldson-Steuart House) (Kentish Inn)
10 Francis Street
Annapolis
Anne Arundel County
Maryland

HABS MD, 2-ANNA,

HABS No. MD-260

Addendum to .
King William's School (Workman House)
10 Francis Street
Annapolis
Anne Arundel County
Maryland

### **PHOTOGRAPHS**

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

Form 10-920 (June 1983)

# UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS MD, 2-ANNA, 39-

## ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY	
Maryland	Anne Arundel		Annapolis	
HISTORIC NAME OF STRUCTURE (INCL	UDE SOURCE FOR	NAME)		HABS NO.
King William's School				MD-260
SECONDARY OR COMMON NAMES OF S	TRUCTURE	<del></del>		
(Anthony Workman Inn) (I	Donaldson-Steu	art House) (Kenti	ish Inn)	
COMPLETE ADDRESS (OESCRIBE LOCA	TION FOR RURAL	SITES)		
10 Francis Street				
DATE OF CONSTRUCTION (INCLUDE SOURCE)		ARCHITECT(S) (INCLUOE SOURCE)		
1696–1700				
SIGNIFICANCE (ARCHITECTURAL AND Perhaps one of the older paneling.				
STYLE (IF APPROPRIATE) Colonia	l elements, t	hough much altere	ed	
MATERIAL OF CONSTRUCTION (INCLU	DE STRUCTURAL :	SYSTEMS) Brick 1	id in Flem	ish and English bond,
now altered in front by having	g been covered			
THE PEAND DIMENSIONS OF STRUCTU	RE <i>(SKETCHED FL</i> ment; rectangu	OOR PLANS ON SEPAF Lar main block w	ATE PAGES A	RE ACCEPTABLE) on a bent axis.
Main block approximately 50'x Main block has central hall f EXTERIOR FEATURES OF NOTE At the	35', 5 bays log lanked by two	ng. Northwest wir main rooms on eac	ng is 35'x2 h side.	5', 4 bays long.
porch, wooden above a brick be	ne center of these	he main block is	a one-stor	y, one bay entrance
Inilactore against the woll Co	olumne and nil	actors bore simpl	a appitala	hut are floring by
scrolled brackets. A wooden see			ss three b	ays of the northwest (see attached sho
An enclosed stair with winders		•	da laantal	at the year common
of the central hall. The west	room on the g	ne second floor, round floor is pa	ns located	yellow pine. Above a
simple base, with bead, are two	tiers of pane			
MAJOR ALTERATIONS AND ADDITION:	S WITH DATES			
ODECENT CONDITION AND LIGH	<u> </u>			
PRESENT CONDITION AND USE $_{ ext{In}}$ $_{ ext{19}}$	34 the Little 1	Photo Studio		
OTHER INFORMATION AS APPROPRIA	<u></u> ГЕ		· · · · · · · · · · · · · · · · · · ·	
SOURCES OF INFORMATION (INCLUOII	VG LISTING ON NA	TIONAL REGISTER, S	TATE REGIST	ERS, ETC.)
Report by Harley McKee,	N.P.S. Archite	ect, submitted 19	964.	
COMPILER, AFFILIATION Eleni Silv	verman, HABS			DATE August 1983
t				

### EXTERIOR FEATURES OF NOTE (Continued from page one)

wing; the balcony has ornamental designs pierced in the vertical board railing.

There are two chimneys at each end of the main block and one in the center of the rear wall. The bracketed bay window on the main elevation is a nineteenth century addition. A modern shop window has been incorporated into the brick foundations of the entrance porch.

The original gambrel roof has been altered in the front of the main block into a single slope; the original pitch of the roof has been retained in the rear elevation, though the roofing material is now sheet metal.

There are shed dormers on the rear elevation at second story level.

The cornice across the main elevation is of 19th century construction, as is the similar cornice on the bay window.

#### INTERIOR FEATURES OF NOTE (Continued from page one)

The panels are surrounded by a bead molding. The cornice is narrow and consists of a cyma recta above a cyma versa. Above each door opening is a horizontal panel. There are two narrow closet doors on the northwest wall, each with narrow molded trim. One door (apparently original) on the northeast wall has six panels, raised on one side and plain on the other, and is an inch thick. The three original doors retain wrought-iron L-hinges. A slightly projecting chimney is centered on the northwest wall. The paneling above the fireplace opening appears to be original, but the marble mantelpiece is 19th century: plain pilasters, a plain frieze with a low Tudor arch along the lower edge and a shelf without bed moldings. The hearth below is of the same marble.

The walls of the south room are papered. The doors and mantel appear to date from about mid-nineteenth century. The windows of the bay window are equipped with folding interior louvered shutters.

The east room contains a dark marble fireplace mantel which appears to date from mid-nineteenth century, as does the ornamental plaster ceiling decoration.